

## New Replacements for Volkmann 9000 Series Drives

Old Volkmann 9000 Series Drives			New SPINDEL Electronics Replacement Drives		
<i>460V</i>			<i>460V</i>		
<i>Type/Rating No.</i>	<i>Rated Power HP</i>	<i>Rated Current A</i>	<i>Type/Rating No.</i>	<i>Rated Power HP</i>	<i>Rated Current A</i>
94003H	3	5	AV-4V006A	4.8	6
94005H	6.8	9	AV-4V014A	11	14
94007H	7.5	11			
94010H	13.5	17	AV-4V021A	17	21
96015H	15	21			
94020H	20	26	AV-4V036A	28	36
94030H	30	39			
94040H	40	50	AV-4V068A	54	68
94050H	50	63			
94075H	75	94	SM-4V096A	75	96
94100H	100	125	SM-4V125A	100	125
94150H	150	190	SM-4V190A	150	190
94200H	200	250	SM-4V250A	200	250
<i>230V</i>			<i>230V</i>		
<i>Type/Rating No.</i>	<i>Rated Power HP</i>	<i>Rated Current A</i>	<i>Type/Rating No.</i>	<i>Rated Power HP</i>	<i>Rated Current A</i>
92003H	3	9	AV-2V011A	4.4	11
92005H	6.8	17	AV-2V022A	8.9	22
92007H	7.5	21			
92010H	10	26	AV-2V038A	15	38

### Notes

New replacement drives would be factory programmed for the application. If provided, SPINDEL Electronics would mark-up the electrical diagrams. Phone support would be provided to facilitate re-wiring and start-up.

### Warranty

The warranty for the new replacement drives is 2 years.

For more information contact SPINDEL Electronics via email at [info@spindel.com](mailto:info@spindel.com)  
or visit [www.volkmanrepair.com](http://www.volkmanrepair.com).